

Product Safety Recall

PIAK REAR TOW-BARS

TO SUIT MITSUBISHI QE PAJERO SPORT (MY 05/2016-11/2019)



Sold by Bapcor Retail outlets
between 1 October 2019 and 31 May 2022

Affected Part numbers:

PK211MBCMPS16
PK211OCMPS16
PK210OCMPS16
PK210NOCMPS16
PK210MBCMPS16
PK210NMBCMPS16



Located on the underside of the towbar on the drivers side.

Defect: The left and right tow-bar attachment bracket may crack causing the tow-bar to detach from the vehicle.

Hazard: If the tow-bar detaches from the vehicle while towing, there will be a loss of vehicle and trailer control which may result in the injury or death of vehicle occupants and other road users.

What to do: Consumers should immediately stop using the tow-bar.

Consumers should contact the store where they first purchased and/or had the tow-bar fitted to arrange for it to be removed from their vehicle and for a full refund.

Contact details: For further information, consumers should contact Opposite Lock Customer Service by phone on 1300 168 616 (Monday-Friday 8am to 5pm), by email at oppositelock-warranty@anaustralia.com.au or via the website at <https://oppositelock.com.au/ol/contacts>

See productsafety.gov.au for
Australian product recall information