

# Product Safety Recall

Polaris RZR Pro XP 4 MY2021-2022



4 affected vehicles  
Sold between 2 January 2021 and 13 September 2022

**Defect:**

Fuel may leak from the fuel pump joint.

**Hazard:**

If fuel leaks near an ignition source it may cause a fire or explosion, increasing the risk of serious injury or death to vehicle occupants.

**What to do:**

Consumers should not operate their vehicle. Consumers should contact their preferred Polaris dealer and arrange a time to book their vehicle in for repairs.

**Contact details:**

To find a local dealer, visit [www.polarisaustralia.com/find-a-dealer/list-view/](http://www.polarisaustralia.com/find-a-dealer/list-view/) or call 1300 654 142.

For further information, consumers should contact Polaris Customer Service on 03 9394 5671.

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**