

Product Safety Recall

Polaris RZR Turbo S & XP Turbo MY2021



**188 affected vehicles
Sold between 23 November 2020 and 12 September 2022**

Defect:

Under certain operating conditions, the vehicle may have an increased risk of clutch failure.

Hazard:

If the clutch fails, clutch components or debris may be ejected from the clutch housing, causing injury to the driver or passenger.

What to do:

Consumers should not operate their vehicle. Consumers should contact their preferred Polaris dealer and arrange a time to book their vehicle in for repairs.

Contact details:

To find a local dealer, visit www.polarisaustralia.com/find-a-dealer/list-view/ or call 1300 654 142.

For further information, consumers should contact Polaris Customer Service on 03 9394 5671.

**See productsafety.gov.au for
Australian product recall information**