


# Product Safety Recall

**MAX Bull Bar for GWM Cannon**  
(Part number MAX-GWMCAN21)



Sold at certain auto part stores between 1 October 2021 and 30 November 2022

**Defect:** Mounts produced in 2021 have been incorrectly manufactured which can lead to the chassis mount cracking when used in rough conditions.

**Hazard:** If the mounts crack, this will cause excessive movement of the bull bar. This can cause damage to the vehicle or the bull bar may detach from the vehicle. This increases the likelihood of an accident occurring which may cause serious injury or death.

**What to do:** Consumers should return to where they had the bull bar fitted for inspection and replacement of any affected mounts.

**Contact details:** Consumers can contact Equipit Group for more information by phone on 07 3204 0311 (8am - 4:30pm Monday to Thursday, or 8am - 4pm Friday) or email on [sales@equipitgroup.com.au](mailto:sales@equipitgroup.com.au)

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**