

Product Safety Recall

Polaris RZR Pro R & RZR Pro R 4 Model Year 2022-2023



4 affected vehicles supplied between 7/11/2022 and 24/12/2022 through Australian Polaris Dealers.

Defect: In some model year 2022-2023 RZR Pro R / Pro R 4 vehicles, the internal rotor inside the alternator may crack and separate while using the vehicle.

Hazard: If an internal rotor of the alternator cracks during use, it poses the risk of fire and serious injury to vehicle occupants.

What to do: Consumers should not operate their vehicle. Polaris will notify consumers once the recall repair procedure has been finalised.

Consumers will then be able to contact their preferred Polaris dealer and arrange a time to book their vehicle in for repairs. To find a local dealer, visit www.polarisaustralia.com/find-a-dealer/list-view/ or call 1300 654 142.

Contact details: For further information, consumers should contact Polaris Customer Service on 03 9394 5620.

See productsafety.gov.au for
Australian product recall information