


Electrical Safety Recall

Powerwize 50Amp Adaptor Lead Range



PW4442, PW4440, PW4444, PW4446, PW4448, PW4449
Sold at Autobarn & Autopro Automotive retail stores
from 1 January 2017 to 11 February 2019

Defect – Some connectors may have been incorrectly wired. The black negative wire has been wired to the positive (+) socket. The red positive wire has been wired to the negative (-) socket.

Hazard – If a consumer uses this product, it may cause a short circuit and increase the risk of a fire leading to serious injury or death.

What to do – Consumers should immediately stop using the product and check that the correct cables are wired to the correct terminals.

Correct wiring: The red wire is connected to the (+) socket terminal and the black wire is connected to the (-) socket terminal.

If you are unsure, please return the product to your nearest place of purchase (Autobarn or Autopro store) at which point consumers may elect to either obtain a full refund or replacement product.

Contact details - You can contact your nearest Autobarn or Autopro store at the following website: www.autobarn.com.au & www.autopro.com.au

**See productsafety.gov.au for
Australian product recall information**