

ELECTRICAL SAFETY RECALL

Bodum Bistro Toaster Model 10709-57AUS-4



IDENTIFICATION:

Bodum Bistro Stainless Steel 2 Slice Toaster Model 10709-57AUS-4 sold exclusively through Spotlight stores from approximately August 2018 until early February 2019. No other Bodum toasters are affected by this recall.

DEFECT:

The product may not comply with the Electrical Safety Standard. Fluctuating voltage issue may cause an electrical shock.

HAZARD

Risk of an electrical shock if users touch the inside heating element when the Toaster is plugged into the power supply and the control lever is not triggered and remains in upper position.

ACTION REQUIRED

Consumers should immediately cease using the Toaster and return it to any Spotlight store for a full refund.

CONTACT DETAILS

For more information concerning this recall contact Spotlight by telephone on 03 9675 4129.

Spotlight
Level 6, 111 Cecil Street
South Melbourne VIC 3205

See www.productsafety.gov.au for Australian product recall information