

Product Safety Recall

Forty Winks Franchising Pty Ltd Saturn Bunk Bed

Sold at Forty Winks stores between 01/06/2013 to 01/04/2019.



Front Guardrail gaps have clear plastic infill panel

Defect This recall relates to the remediation offered to consumers as a result of previous recall PRA2015/14628. The plastic infill panel which was installed on the holes in the guardrail may become detached from the upper bunk.

Hazard If the fitted panel becomes detached, the holes in the guard rail may pose an entrapment hazard to children.

What to do All known consumers will be contacted by Forty Winks to discuss their options for remediation.

For further information, consumers should contact Forty Winks on (03) 9574 5100 or email reception@fortywinks.com.au

Please note: If the bed was sold before March 2015, the previous recall PRA2015/14628 is still binding and a panel should be installed on the holes in the guard rail to ensure that there is no entrapment hazard.

If a panel has already been installed as a result of the previous recall, consumers will now need to ensure that this is correctly affixed by contacting Forty Winks. If a panel has not been installed as a result of the previous recall, consumers should contact Forty Winks immediately to arrange repairs.

**See productsafety.gov.au for
Australian product recall information**