

Product Safety Recall

Kubota Z100 Series Zero Turn Mowers



Model	Serial Range
Z122EBR-48-AU	13664 - 14039
Z121SKH-48-AU	11543 - 11601
Z125EBR-54-AU	11450 - 11477
Z125SKH-54-AU	11021 - 11063

Supplied 2018 and 2019

Defect: The throttle wire assembly may not have been routed properly from the factory.

Hazard: The throttle wire assembly could make contact with internal electrical wiring, posing a fire hazard.

What to do: Stop using the affected products until the throttle wire assembly has been replaced with a new throttle wire cable and re-routed free of charge by your local Kubota dealer.

**See productsafety.gov.au for
Australian product recall information**