

Product Safety Recall

Certain Husqvarna TS 242 and TS 246 model Lawn Tractors manufactured between February 2015 and November 2017



Defect- The fuel line in the identified tractors was not routed behind the tank guard. This may allow the fuel line to contact and rub against the transmission belt.

Hazard- If the fuel line contacts or rubs against the transmission belt fuel could leak from the fuel line, posing a risk of fire.

What to do- Consumers should immediately stop using the affected lawn tractors and contact their authorised local Husqvarna dealer to make arrangements for a free repair.

Contact details- Please contact your authorised local Husqvarna dealer. Alternatively, contact Husqvarna Australia through technical.service@husqvarna.com.au. Further information is also available on the website husqvarna.com.au.

**See productsafety.gov.au for
Australian product recall information**