

Product Safety Recall



Tripp Trapp® Newborn Set

Sold at Baby Bunting, David Jones and Independents - February 2019 – June 2019

Defect When re-assembling the Newborn Set harness after washing, there is a risk that consumers can assemble the harness incorrectly. This may lead to one or more harness attachment points detaching.

Hazard If the defect occurs while the child is seated in the harness, they could fall and be injured.

What to do Consumers should immediately stop using the Tripp Trapp Newborn Set and go to reclamations.stokke.com/newbornupgrade to verify whether their product is affected. If the Newborn Set is verified as affected, consumers should continue their registration to receive instructions on how to get their product repaired.

Contact details Please visit the above website for verification of product and registration. For more information, Stokke can be reached via e-mail at info@exquira.com.au or by calling 1300 814 557.

**See productsafety.gov.au for
Australian product recall information**