

# Product Safety Recall



## Sea-Doo GTX 230 and 300, RXT 230 and 300, and Wake PRO 230 Watercrafts MY2019

Available for sale by BRP between 1 August 2018 and 23 July 2019

**DEFECT** Due to inappropriate front fastener torque, the intake grate may detach from the vehicle while in use.

**HAZARD** Riding at speeds over 88km/h without an intake grate may cause unpredictable vehicle behaviour. This may lead to occupant ejection, increasing the risk of serious injuries or death.

**WHAT TO DO** Consumers should immediately cease using the watercraft and contact an authorised Sea-Doo dealership to arrange a time to have their watercraft repaired, once parts are available.

**Contact details** To find a local Sea-Doo dealer, visit <https://au.sea-doo.com/dealer-locator.html>

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information