


Product Safety Recall



Mares XR BCD Buoyancy Compensation Vest Inflator

Available for sale by Mares between
14 September 2018 and 14 March 2019

DEFECT Due to insufficient torque applied in the manufacturing process, the inflator's deflation button may unscrew.

HAZARD If the inflator's deflator button unscrews, there may be a loss of buoyancy, which poses a drowning hazard for the wearer.

WHAT TO DO Consumers who have an affected product that has not yet been repaired should take their inflator to the retailer where the product was purchased to arrange repair.

Repaired inflators are marked with an engraved 'X' near the serial number. No further action is required if your inflator has this mark.

Contact details For more information, contact Mares on 07 3386 1210 or via info@au.mares.com

See productsafety.gov.au for
Australian product recall information