

# Product Safety Recall



## Torin Australia – Hydraulic Trolley Jack

Sold at Auto One Australia stores between 18.8.17 and 31.12.17

**Defect** The hydraulic trolley jack is supplied with a rubber head cap, which makes it non-compliant with the mandatory standard Consumer Goods (Trolley Jacks) Safety Standard 2017.

**Hazard** The jack has not been tested with the rubber head cap attached and therefore no longer meets the mandatory standard.

**What to do** Consumers should remove the rubber head cap from the jack before use.

**Contact information** For further information consumers can call Torin Australasia on 1800 833 800 or email [info@torinjacks.com.au](mailto:info@torinjacks.com.au).

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information