

ELECTRICAL SAFETY RECALL

Carrier Hi-Wall & Cassette Split Air Conditioning Systems



Identification:

The following models of Carrier air conditioners are affected by this recall:

38SHV052P1	38QHF080	38SHV071P1	38TSV067P1
38SHV087P1	38SHV135P1	38SHV165P1	38TSV110P1
38TSV130P1	38SHV105P1	38TSV080P1	

Where the product was sold:

Sold in Australia between November 2013 and June 2019

Defect:

The fan motor located in the outdoor condensing unit may fail.

Hazard:

If the fan motor fails, the outdoor condensing unit may have a Risk of Fire, which may result in property damage and/or personal injury.

Action required:

Consumers should immediately:

- Stop using the air conditioner
- Contact Carrier at the details below so that Carrier can make arrangements to carry out the required re-work at your premises free of charge.

Carrier Contact details: Phone 1800 959 554, email carrier.rework@ahi-carrier.com.au or visit the website: www.carrierrework.com.au

**See productsafety.gov.au for
Australian Product Recall Information**