

Product Safety Recall



STIHL Chainsaw / Concrete Cutter

Models MS 461, MS461-R and GS 461

With serial numbers 173092800 to 181993952 inclusive

Sold at STIHL dealerships since 2012.

Defect


In some recalled machines the fuel suction hose may be pinched or have a small hole in it.

Hazard

If the defect is present a fuel leak could occur. No injuries have been reported but a fuel leak might have hazardous consequences.

What to do

If the serial number on the motor housing of your unit is between 173092800 and 181993952 inclusive, do not use the machine any more. Take it to a servicing STIHL dealer to be checked. If the defect is found, a replacement fuel suction hose will be fitted at no cost to the consumer.



Serial number location

Contact details

Contact your nearest servicing STIHL servicing dealer (see stihl.com.au/dealer-locator.aspx), phone STIHL on (03) 9215 6666 between 9am-5pm, Mon-Fri or email products@stihl.com.au.

See productsafety.gov.au for
Australian product recall information