

# Product Safety Recall

## YAMAHA PORTABLE GENERATOR EF2000iS



### Affected Range

7PB 0329803 ~ 7PB 0330916 - 2018

7PB 5080473 ~ 7PB 5080496 - 2019

### CORRECTIVE ACTION FOR FUEL TANK CRACKING

#### WHAT IS THE DEFECT?

The moulded area of the fuel tank to which the fuel valve is mounted, was moulded at the incorrect temperature.

#### WHAT ARE THE HAZARDS?

The tank material can be too brittle allowing the tank to crack. If the fuel tank cracks, the risk of fire increases, resulting in severe injury or death.

#### WHAT IS THE REMEDY?

Affected units must have a new correctly moulded fuel tank installed. Owners are required to contact their nearest **Yamaha Dealer** to have this fuel tank replaced free of charge. For details of your local dealer visit [www.yamaha-motor.com.au](http://www.yamaha-motor.com.au) or call 1300 593 600.

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information