

Product Safety Recall



Cub Cadet Pro Z and Tank S/Z ride on lawn mowers
Pro-Z 554S, Pro-Z 760S, Pro-Z 972S, SZ60
Sold as follows through various Cub Cadet dealerships

Australian Product	Model	Available for Sale in Australia
SZ60	53AI2PUD330	1/01/2011
Pro Z 554 S	53AIHJUN330	5/07/2017
Pro Z 760 S	53AIHKUV330	12/02/2018
Pro Z 972 S	53AIHMUY330	12/02/2018

Defect There is a potential weakness in the nut and bolt used to secure the bottom steering shaft to the steering gearbox. The resulting inadequate clamp load at the yoke-to-shaft connection can result in excessive play or looseness in the steering.

Hazard This may potentially result in a reduction or loss of steering control, posing an accident risk.

What to do Consumers should stop using the ride on mower, check the manufacture date on the model plate located under the seat and contact their selling dealer, closest dealer or authorised repair agent to arrange an inspection and if necessary, repair.

Contact details For details of Cub Cadet dealerships, visit www.cubcadet.com.au. MTD Products Australia Pty Ltd, Phone: 1300 951 594 Mon-Fri 9am-5pm, Email: Luke.Turner@mtdproducts.com.

**See productsafety.gov.au for
Australian product recall information**