

Product Safety Recall



Thetford 3-Way Absorption Fridge

Models: N304M.3R, N304M.3L, N504M.3FR, N504M.3FL

Supply Dates: 15/09/2017 to 15/02/2018

Range of serial numbers possibly affected: 27381864 and 28220540

Defect The gas control valve pressure test point nut may not be correctly tightened.

Hazard If the test point nut is not correctly tightened it could cause a gas leak, potentially leading to a fire.

What should consumers do? Consumers should check the serial number on the label in the interior cabinet of the fridge. If the serial number falls within the range detailed above, consumers should immediately discontinue using the product on gas. Consumers should then go to www.thetfordfridgecheck.com to find out if their fridge is affected in the recall. Consumers should then:

1. Enter the product serial number and follow the prompts where needed.
2. or call Thetford on 1800 503 100 to check if the fridge is affected.

Consumers will be directed to the nearest authorised service agent to organise a repair.

For further information consumers can contact Thetford Australia on 1800 503 100 Monday to Thursday 8am to 4.45pm (EST) & Friday 8am - 2pm (EST), by emailing recall@thetford.com.au or go to <http://www.thetfordfridgecheck.com>.

**See productsafety.gov.au for
Australian product recall information**