

Product Safety Recall



FIXE-1 PLX hanger installed



Position of the serial number on the rear side



Intertrek Pty Ltd — Fixe Climbing PLX Hanger-1

Affected products have a batch number between 0116 and 2216 & the first two figures are between 01 and 22 and the last two are always 16.

Defect: A tendency towards oxidation in marine environments that is very high and unusual.

Hazard: Highly corroded anchors may fail and although there is almost redundancy in climbing anchor systems, injury may occur.

What to do: Intertrek advises customers and consumers to inspect any product not yet installed for the affected batch number and to return affected product for a full refund or replacement with non-affected product.

For any anchors already installed, it is very difficult to ascertain the batch number and so Intertrek advises end users to inspect anchors for any signs of rust or corrosion before use

Contact details: For any questions or concerns please contact us at:
sales@intertrek.com.au

See productsafety.gov.au for
Australian product recall information