

Product Safety Recall



SR Suntour Front Suspension Forks on SCOTT Sportster Bikes

SCOTT recalls SR Suntour NEX and NCX suspension forks on SCOTT Sportster bikes with of model year 2011, 2012 and 2013

Sold through authorised SCOTT dealers since about May 2010.

Defect: The dropouts on the suspension fork can break.

Hazard: If the defect occurs during use the rider may lose control of the bicycle, potentially resulting in a serious fall injury.

What to do: Please stop using your Sportster immediately and return it to any official SCOTT dealer to have the affected fork repaired at no cost.

Contact Details:

For further information please visit www.scott-sports.com and access *safety and recalls*, email SCOTT at recall@scott-sports.com or call 0800 999 499

Australian Importer/Distributor

Sheppard Cycles Australia

47-67 Westgate Drive, Altona North VIC 3025, PO Box 490, Altona VIC 3018

See www.recalls.gov.au for
Australian Product Recall Information