


ELECTRICAL SAFETY RECALL



Rating label

Spa Industries Pty Ltd is recalling class II (double insulated) M Spa inflatable spas supplied between 2012 and 2014.

The recalled models B110 and B112 are marked with the approval number SAA121806EA and double insulated symbol  on the protective cover of the control box.

Defect: A fault in the heating element assembly insulation may cause the water/wet parts to become live

Hazard: Risk of electric shock

Where the product was sold:

Aqua North Pty Ltd	Ballarat Pools and Spas	Bairnsdale Swim and Ski
BG's Pools and Spas	Spa Industries	Enviro Spa (Nature Spa)
Hervey Bay Pools and Spas	InStyle Pools and Spas	Just Spas Chelsea Heights
Just Spas Essendon	Just Spas Hallam	Just Spas Hobart
Just Spas Launceston	Melton Pools and Spas	The Pool Depot
Poolside Albury/Wodonga	Poolside Pakenham	Wilton Industries
Spa and Pool Parts Online(Spa Industries)		Spa Lifestyle
Springfield Pool and Spa Supplies		Xquisite
Riverland Creative Gardens		

Action Required:

- Immediately discontinue using the spa and unplug it from the socket outlet.
- Customers should contact their retailer to arrange for repair or replacement by selecting one of the options listed below.
 - Obtain a new electric control box to replace the old class II control box.
 - Arrange for the rework of your spa.
- For further information related to this recall, please contact Spa Industries Pty Ltd on 03 9702 3144 or by email to info@spaindustries.com.au

See www.recalls.gov.au for
Australian product recall information