

ELECTRICAL SAFETY RECALL

TOSHIBA PC Power Cord

AC Power Cord, model: LS-15

Sold with Toshiba PCs between Sept 2010 - Jun 2012



IDENTIFICATION:

Some Toshiba notebook computers sold between September 2010 - June 2012, were shipped with “LS-15” branded AC Power cords. The location of the “LS-15” marking is on the portion of the cord that plugs into the AC Adaptor, as shown in the red box in the above image.

These AC Power cords were supplied with Toshiba PCs sold in **Australia and New Zealand**.

Note: **not all** Toshiba PCs were sold with the affected AC Power cord. You will need to check if your AC Power cord is affected by entering your PC’s Model and Serial Number on the recall check webpage listed below.

HAZARD:

Some affected “LS-15” AC Power cords may overheat and burn.

ACTION REQUIRED:

1. Stop using your Power cord immediately
2. Visit the Toshiba website, www.mytoshiba.com.au/support to check if your Power cord is affected.
3. If affected you will be asked to register to receive a replacement AC Power cord

For further information contact
Toshiba Australia Pty Ltd
13 30 70

See www.recalls.gov.au for Australian product recall information