

PRODUCT SAFETY RECALL

Toro TimeCutter® 2015 Ride-on Mowers




Figure 1
Under the seat

1. Model and serial number plate



Toro Australia Pty Ltd is conducting a product recall of fuel filters in the Toro TimeCutter® 2015 Ride-on Mowers listed below.

Model	Name	Serial Numbers
74710	TimeCutter® SS 3225 32"	315000876 – 315002048
74720	TimeCutter® SS 4200 42"	315000101 – 315003342
74750	TimeCutter® MX 3450 34"	315000101 – 315001155
74784	TimeCutter® Zero Turn Tractor SW 4200	315000340 – 315001172

The products were sold nationally by Authorised Toro dealers during 2015. The model and serial numbers are on a metal plate located under the seat as shown in the image above. Contact Toro using the contact details below if you have any questions regarding whether your product is included in the recall.

DEFECT: The fuel filter may fail due to becoming excessively brittle.

HAZARD: If the fuel filter fails it may result in a fuel leak which may present a fire hazard.

WHAT TO DO: Stop using your mower immediately and contact Toro using the contact details below to arrange replacement of the fuel filter.

CONTACT DETAILS: If you have any questions regarding this issue, including whether your product is included in this recall or for the details of your local Toro dealer please contact Toro on 1800 356 372 or email ProductRecall.AU@toro.com

See www.recalls.gov.au for Australian product recall information