



Product Safety Recall



Do you own this product?

OEX EFI Inline fuel filter

Part number: OXFF62

Sold separately and as part of Repco filter service kits RFSK0030C and RFSK0032C.

Dates sold: 10/08/2023 – 16/01/2024



Why the product is recalled: The fuel filter's thread is too long, creating a gap when fitted and allowing fuel to leak.

Hazard: There is a risk of a serious injury or death and/or property damage if fuel leaks in the presence of an ignition source and catches fire.



1. Consumers should immediately return to their place of purchase or installation to have the fuel filter inspected.
2. Consumers will be offered a free replacement of the fuel filter.
3. Consumers who cannot return their vehicle to the place of purchase for inspection should contact GPC Asia Pacific.



Ask our staff to find out more about the recall.

recalls@gpcasiapac.com

1300 301 072



Purchased from: Repco Auto Parts



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2024/20032

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information