



Product Safety Recall



Do you own this product?

Canyon Bicycles GmbH — Canyon Speedmax CF (R073) and Canyon Speedmax CF (R41) triathlon bicycles with V21 Aerostem

Affected models:

- R073
- R41

Model years 2016 – 2024.

Dates sold: 1 January 2016 – 30 April 2024



Why the product is recalled: The stem and handlebar may crack, leading to breaking or detachment. This may occur after impacts such as striking a pothole or kerb.



Hazard: There is a risk of injury from a fall if the stem and handlebar break or detach while the bike is being ridden.

This defect has occurred.



Consumers should stop using the bicycle immediately. Consumers should check [Canyon's website](#) to arrange for a free inspection and, if necessary, repair by a professional bike mechanic.



Contact Canyon on 1800 959 071 (between 9:00am – 5:00pm (AEDT) Monday – Friday) or visit [Canyon's website](#).



Purchased from: [Canyon Bicycles website](#).

PRA2024/20353

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information