

Product Safety Recall

Yamaha Youth Quad Bike Model YFM90R (RAPTOR) 2016 and 2017

Front & Rear Brake Shoe Exchange

Affected Serial Number Range



MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
YFM90R	2016	AB11Y	202	6467
	2017	AB11Y	6468	6891
	2017	AB11Y	6892	8909

Yamaha Motor Australia Pty Ltd is conducting a RECALL CAMPAIGN on certain YFM90R (RAPTOR) Model ATV Motorcycles.

WHAT ARE THE DEFECTS?

Front and rear brake shoes in affected units (and these parts sold as spare parts) may contain asbestos.

The importation of asbestos or goods containing asbestos into Australia has been prohibited under the Customs (Prohibited Imports) Regulations 1953 since 31st December 2003.

WHAT ARE THE HAZARDS?

Available information indicates that these affected units do not pose a measurable health risk through normal use.

Exposure to asbestos can result in asbestos-related diseases.

WHAT SHOULD CONSUMERS DO?

Consumers should not perform any maintenance, repairs or modifications on these affected units that may involve contact with or disturbance of the brake shoes.

You will receive further notice on what to do to have the brake shoes replaced free of charge at a Yamaha Dealer.

For further information please contact Yamaha.
Email: cr@yamaha-motor.com.au Phone: 1300 593 600

See productsafety.gov.au for
Australian product recall information