



Product Safety Recall



Do you own this product?

Roy Gripske & Sons Pty Ltd – Voltage regulator in Kawasaki general purpose engines

Voltage regulators (part no. 21066-0785) installed in select Kawasaki general purpose engines primarily used in ride on lawn mowers. Find affected model numbers and serial numbers on the [recall notice](#).

Dates sold: 1 April 2021 – 19 December 2023



Why the product is recalled: The voltage regulators in affected Kawasaki general purpose engines can malfunction. The voltage regulator can catch fire at any time, even if the engine is off or not in use.

Hazard: There is risk of serious injury, death and/or damage to property if the voltage regulator catches fire.



Action required:

1. Stop using the affected engine, or the product it is installed in, until it has been repaired.
2. Disconnect the negative battery cable and secure it away from the negative battery post. If you are unsure on how to disconnect the battery, see the [battery disconnection instructions](#) or contact your [local GA Spares dealer](#).
3. Contact your local GA Spares dealer to arrange repair.



For more information contact Roy Gripske & Sons Pty Ltd via email sparesqld@rgs.com.au or phone 1300 363 004 (8:30am to 4:30pm, Monday to Friday).



Purchased from: [GA Spares dealers](#)

PRA 2024/20126

See productsafety.gov.au for
Australian product recall information