

ELECTRICAL SAFETY RECALL

Moretti 11 Fin Oil Column Heater Model No. MNDB1M-III, Batch 12/15 (OLN No. 9129)



IDENTIFICATION:

Check for unit identification details – **Model No.**, **Batch Code** and **OLN Code** on the rating label located on side of the front panel.

Affected heaters have **Model No. MNDB1M-III**, **Batch Code 12/15** and **OLN 9129** and were sold through **BUNNINGS** from 24 February 2016 to 3 May 2017.

DEFECT:

A potential manufacturing defect may cause the heater control panel to overheat, and in some cases to melt and catch on fire.

HAZARD:

Risk of burns and a risk of fire.

ACTION REQUIRED:

Stop using the heater immediately and return it to the nearest Bunnings store as soon as possible for a full refund.

CONTACT DETAILS:

For any further information, please contact the Yale Prima Call Centre on **1300 366 155** in Australia.

See www.productsafety.gov.au
for Australian Product Recall Information