

Product Safety Recall



Argon 18 2012 Model E-118 Bicycle

Sold through Argon 18 retail outlets from October 2011

Defects - *The stem reversible spacer fitted to this model may not generate sufficient tension to securely fasten the handlebar to the stem and in certain circumstances may allow the handlebar to rotate.*

Hazards - *A rider could lose control of the bicycle and sustain personal injury.*

What to do - *Consumers should not ride the bicycle and should return it to their nearest authorised Argon 18 retailer for modification, or contact FRF Sports.*

Contact Details - *If you need assistance please contact Michael Rabbets at FRF Sports on 02 95599000 or alternatively, by email: michael@frf.com.au*

**See www.recalls.gov.au for
Australian Product Recall Information**