

Electrical Safety Recall

Bosch PSS Sander Series PSS 2, PSS 20, PSS 190, PSS 200, PSS 250 and PSS 2000. Serial number 786xxxxxx - 788xxxxxx. Sold to Australian hardware stores from June 2007 to August 2009.

Defect A defect of the ventilation wheel could cause a break of the device housing.

Hazard If the housing is broken then smaller parts of the ventilation wheel could be ejected, and the risk of injury cannot be excluded. There is the possibility of electric shock if live components were exposed from broken housing, although there have been no reported incidents of this.

What to do We kindly ask that consumers immediately stop using the sander and visit www.sandercare.com to find out if the sander is affected. Alternatively contact the hotline on 0011 800 8364 6704 for details on how to receive a replacement model.

Contact Details

Website: www.bosch-do-it.com.au or www.sandercare.com

Sander Hotline (freecall): 0011 800 8364 6704

Email: CustomerService.PT@au.bosch.com

We apologise to our retailers and customers for any inconvenience it has caused.



PSS 250 AE



**See www.recalls.gov.au for
Australian Product Recall Information**