

Product Safety Recall



Boody Sleeveless Bodysuit

SKU: BSCHNB, BSCH03, BSCH36, BSCH12

Batch number 160708 **only**

Sold from November 2016 at www.boody.com.au and various retailers

Defect There is a risk of press studs becoming dislodged from the garment.

Hazard If a press stud is dislodged and swallowed, it may pose a choking hazard to the infant.

What to do Consumers should immediately check their bodysuit to determine if it is part of the affected batch (160708). If you are in possession of an affected bodysuit, please cease using the product and return the item to Boody Australia for a full refund or replacement product.

Contact details You can contact Boody Australia Pty Ltd on 02 7201 5321 Mon-Fri 9am-5pm, via email at recall@boody.com.au or for more details (including locating the batch number) visit www.boody.com.au.

**See productsafety.gov.au for
Australian product recall information**