

ELECTRICAL SAFETY RECALL

AGP DE25 DUST EXTRACTOR



IDENTIFICATION: AGP DUST EXTRACTOR MODEL DE25
These units were sold at all TradeTools Stores.

HAZARD: **Risk of Electric Shock**

The connector for the dust bin vibrating “filter shaker” motor has been incorrectly assembled. If the dust bin is removed without first disconnecting from the supply as instructed, live parts may be accessible whilst the lid is removed.

ACTION REQUIRED:

Cease using the product immediately, disconnect from supply. Contact any TradeTools store to make arrangements to modify/repair the design defect to meet Australian electrical safety Standards.

For further information

TradeTools Pty Ltd

Phone : 07 5540 6400

Email : info@tradetools.com

See www.productsafety.gov.au for Australian product recall information