

Product Safety Recall



IVECO TRUCKS AUSTRALIA LIMITED

MY14 Daily 4x2 Cab Chassis models – 50C and 70C
MY14 Daily 4x2 Van models – 35S and 50C

DEFECT:

Moisture may enter the air bag module because of a misalignment of the air conditioning system drain tube.

HAZARD:

Moisture in the air bag module may cause the air bag/s to deploy unexpectedly, potentially causing an accident or injuring passengers.

ACTION REQUIRED:

This defect is the subject of an existing product campaign where all affected customers were notified. All remaining vehicle owners who have not had the recall conducted will be contacted by Iveco Trucks Australia and its dealers advising them of this recall. All affected customers should take their vehicle to their nearest authorised Iveco dealership where the recall will be conducted. A letter will also be sent by registered post to all owners of affected vehicles. If you are not contacted but you think your vehicle is affected then please contact Iveco Trucks Australia on 1800 4 Iveco.

FOR FURTHER INFORMATION

IVECO TOTAL CARE

TOLL FREE: 1800 4 IVECO (Australia Wide)

Email: ivecocare@au.iveco.com

**See www.recalls.gov.au for
Australian Product Recall Information**