


ELECTRICAL SAFETY RECALL



Ideal Sources Pty Ltd is recalling 45 units of M Spa inflatable bubble spas supplied between 2013 and 2014.

The affected model is B141. These spas are marked with the approval number SAA121806EA and double insulation  symbol.

Defect: A fault in the heating element assembly may cause the water/wet parts to become live.

Hazard: Risk of electric shock.

ACTION REQUIRED:

- If you believe you have purchased M Spa, model B141, immediately stop using the spa and unplug it from the socket outlet.
- Contact Ideal Sources Pty Ltd with a proof of purchase to arrange for a full refund or a replacement of the control box of the spa.

For further information related to this recall, contact Ideal Sources Pty Ltd on 03 9587 7706 or email enquiries@idealsources.com.au

See www.recalls.gov.au for
Australian product recall information