


ELECTRICAL SAFETY RECALL

LED Recessed Emergency Light


LifeGuard 1 BEL-LG1, LifeGuard 2 BEL-LG2, Nikko Pancake NIK-PANCAKE-EXE




IDENTIFICATION:



P/N: NIK-PANCAKE-EXE



P/N: BEL-LG1




P/N: BEL-LG2

Part numbers of the products are clearly shown on the control box as illustrated above. The complete product consists of a recessed LED disc, a control box and a battery pack. The defect is located in the control box.

Units sold nationally by all major Electrical Wholesalers between 14th May 2013 and 15th November 2013

DEFECT:



There exists a manufacturing fault where a small number of products have untrimmed input power terminals, located at the underside of the control box. Our internal review shows that there are approximately 1 in 25 products with the defect. The untrimmed terminals could potentially extend to, or close to, the surface of the underside of the control box, where a small ventilation cavity exists.

HAZARD:

Contact with these exposed input terminals, whilst the product is connected to power, could cause electric shock.

ACTION REQUIRED:

Distributors and contractors should carefully inspect all installed or stocked products immediately. Any products affected by the manufacturing fault should be returned to your nearest MPower branch for an exchange with a replacement product.

For further information, please direct all calls and any queries concerning this recall to the MPower's support line on **1300 733 004** between 9am and 5pm (Mon-Fri) or email info@mpower.com.au

See www.recalls.gov.au for Australian product recall information