

# Product Safety Recall

## Sunbeam (Rechargeable) SM8700 StickMaster Cordless Stick Blender

Sunbeam Corporation Ltd takes product safety very seriously and wishes to advise customers of a product safety recall of the Sunbeam (Rechargeable) SM8700 StickMaster Cordless Stick Blender sold in retail outlets since May 2011.

The model number of the affected product is printed on the back of the hand piece and on the rating label on the charging base as shown below.



**No other Sunbeam Stick Blenders are affected by this recall**

**Defect:** In rare cases the internal lithium-ion rechargeable battery may overheat.

**Hazard:** Overheating batteries are a potential fire hazard.

**What to do:** Customers should immediately unplug the blender charger, cease using the product and contact Sunbeam for a replacement. Customers should call 1300 782 587 (8:30am – 5:30pm AEST Monday to Friday) or visit [www.sunbeam.com.au/SM8700recall](http://www.sunbeam.com.au/SM8700recall) for further information and assistance.

Sunbeam Corporation Ltd sincerely apologises for the inconvenience this may have caused.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information