

Product Safety Recall

Easton Arrow Axis

Size 300 batch number 13169686

Size 340 batch number 13170143

Size 400 batch number 13170142

Size 500 batch number 13169487

Sold at Pat's Archery and Highland Archery Suppliers March – June 2013



Defect Arrow shafts in the affected batches may have a small blemish on the surface of the shaft approximately 10.5 inches (or 25cm) from the point end.

Hazard Arrows in the affected batches could have a weakness and break after launching or hitting a target, causing injury to

the archer or other persons in the vicinity.

What to do Consumers should immediately stop using the arrow shafts and contact Easton Technical Products or Pat's Archery for a free replacement. Consumers that return six affected arrows will receive an additional arrow with the replacements.

Contact details You can contact Easton at www.eastonarchery.com or <http://axisrecall.com>. Pat's Archery can be contacted at www.pats-archery.com, (08) 8552 6722 or at 15 Grantley Avenue, Victor Harbour SA 5211.

See www.recalls.gov.au for
Australian Product Recall Information