

Product Safety Recall



BREMBO BRAKES IN F4 RR AND F4 RC 18RC01

Defect - the BREMBO front brake pump may be subject to potential malfunction

Hazard - if the defect occurs while motorcycle is in use it may result in loss of vehicle control

What to do - consumers should immediately stop using the motorcycle and contact their nearest MV Agusta Dealer to book in a replacement of the front brake master cylinder

Contact Details - you can contact your nearest dealer by visiting www.mvagusta.com.au/dealerships

**See productsafety.gov.au for
Australian product recall information**