

# Product Safety Recall



## ENVY REAPER BAR V3

Batch 3185 and 3186

**DEFECT** In some instances the weld to the top section of the bar may fail

**HAZARD** If the defect occurs whilst riding it could cause injury to the user

**WHAT TO DO** Consumers should immediately stop using the bars and contact their place of purchase to receive a replacement bar or full refund of purchase price

**CONTACT DETAILS** Please contact Metal Core Distribution via email [warranty@metalcoredistribution.com](mailto:warranty@metalcoredistribution.com) or by phoning (07) 3209 6408, if you have any issues with your replacement or refund

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**