



# Product Safety Recall



## Do you own this product?

### Gossamer Pro AGX+ CK-6037 cranksets

Serial number ranges starting with B1 through B3

Dates sold: 01/01/2022 – 31/12/2022



**Why the product is recalled:** The crank arm can loosen and may detach from the spindle while in use.



This defect has occurred.

**Hazard:** There is a risk of accident and serious injury to the user if the crank arm detaches from the bicycle while being used.



1. Consumers should stop riding bikes with affected cranksets immediately.
2. Consumers should return to their preferred dealer for inspection and to have their crankset replaced.



Ask our staff to find out more about the recall.

[Recall-Asia@fullspeedahead.com](mailto:Recall-Asia@fullspeedahead.com)



Purchased from: Full Speed Ahead & Various bicycle dealers



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2024/20175

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information