

Product Safety Recall



PRODUCT: 800ml BLUE RUBBER HOT WATER BOTTLES

DEFECT: The 800ml hot water bottles have been identified as not having the required thickness of rubber as specified in the Trade Practices (Consumer Product Safety Standard) (Hot Water Bottles) Regulations 2008.

HAZARD: There is concern that this hot water bottle may leak, split or burst causing injury.

DATES SUPPLIED: May 2011 – June 2011.

WHAT TO DO: Consumers should cease using this product immediately and return to this store for a full refund.

SUPPLIER INFORMATION

Yin Yang (Aust) Pty Ltd trading as Discount Market

Contact Jenny Ye on 9808 5639

See www.recalls.gov.au for
Australian Product Recall Information