

ELECTRICAL SAFETY RECALL

IDENTIFICATION:

Mechpro Model: MP2540
2.5 HP Air Compressor
direct drive 40 litre air tank



Sold by Repco stores nationally between December 2009 and August 2011.

Defect: A manufacturing defect may give rise to a short circuit in the motor potentially causing it to overheat.

Hazard: Risk of fire, due to overheating of various components in the compressor motor, the plastic cover may catch fire.

What to do: Customers should immediately stop using the product and return the compressor to your nearest Repco store for a refund or replacement.

Contact: For more information call **1800 268 876** or

Austech Industries Pty Ltd
PO Box 715, Archerfield
Qld Australia 4108
(07) 3723 1500

www.austechindustries.com.au

See WWW.recalls.gov.au for
Australian Product Recall Information