

# Product Safety Recall



## Heavy Duty Allin Towbar installed to

1. **ISUZU DMAX** manufactured from 10/2008 to 06/2012 with factory rear step bumper bar.  
Models LS, LSM, LSU and LE Model Variants

Towbar Install or purchase dates 10/2008 to 08/2014

1. **Holden RA Rodeo 4WD** manufactured from 01/2006 to 07/2008 with factory rear step bumper bar

Towbar install or purchase dates 01/2006 to 08/2014

2. **Holden Colorado 4WD** manufactured from 07/2008 to 06/2012 with factory rear step bumper bar

Towbar install or purchase 07/2008 to 08/2014

**Defect** - In some circumstances a towbar fitting component (spacer tube) may be unsuitable and may cause movement between the towbar arm and vehicle chassis.

**Hazard** – Continual movement between the towbar arm and chassis may cause damage to the vehicle chassis

**What to do** – Vehicle owners should immediately stop using the towbar and contact Allin Towbars to organise a vehicle inspection and replacement of fitting components.

**Contact Details** – Allin Towbars (08) 8352 5155 – [www.allintowbars.com.au](http://www.allintowbars.com.au) – or email [admin@allintowbars.com.au](mailto:admin@allintowbars.com.au)

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information