

Attachment B

Product Safety Recall

RECARO Racing Seats "Pole Position SPG (FIA)" and "Furious SPG (FIA)"



Identification:

The possibly affected seats can be identified by their part numbers, RECARO "Pole Position SPG (FIA)" starting with 070.98.XXX, RECARO "Furious SPG (FIA)" with 070.78.XXX. In addition both seats can be identified by the name "Pole Position" and the common homologation number CS.997.00 on the label on the side of the backrests.

Product Issue:

Cracks can occur in the seat shell in the area of the front fixation to the steel adapter connecting the seat with the vehicle floor. Those cracks can potentially lead to a detachment of the shell from the adapter.

Hazard:

In the case of an accident this can possibly lead to a possible risk of injury to the driver or loss of control over the vehicle.

Action required:

End customers shall refrain from using these seats immediately and contact RECARO on +49 202 2515 620, 24 hours, 7 days a week, for further information.

See www.recalls.gov.au for
Australian Product Recall Information