



## Product Safety Recall

### Kawasaki engines in Toro Ride on Lawn Mowers, Trenchers, Stump Grinders and Aerator

XLS 420T Lawn Tractor Model 71255  
ZS 4200T CE TimeCutter Model 74386  
ZS 5000 CE TimeCutter Model 74387  
ZS 4200TF TimeCutter Model 74390  
ZX4820 CE Titan Model 74920

ZX5420 CE Titan Model 74924  
ZX6020 Titan Model 74843  
30 inch Stand On Aerator Model 23518  
TRX-26 Dedicated Trencher Model 22974  
STX-26 Dedicated Stump Grinder Model 23210

Toro Australia Pty Ltd is undertaking a product recall of the above Toro machines with Kawasaki engines with serial numbers that start with 312 eg 312000108. The products were sold nationally in Bunnings stores and by authorised Toro dealers from October 2011.

Go to [www.toro.com.au](http://www.toro.com.au) for more information on the products including product images.

**Defect:** Fuel filters in the Kawasaki engines supplied with the machines may be faulty and have the potential to leak fuel from a welded seam on the filter body.

**Hazard:** Leaking fuel poses a potential fire hazard

**What to do:** Stop using the product immediately and contact your local Toro dealer to arrange for the engine in your machine to be inspected and if necessary a replacement filter to be installed on your machine.

**Contact details:** If you have any questions regarding this issue, including whether your product is included in this recall or for the details of your local Toro dealer please contact Toro on 1800 356 372 or email [ProductRecall.AU@toro.com](mailto:ProductRecall.AU@toro.com)

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information**