

# Product Safety Recall



**SUPPLIER: SPECIALISED FORCE PTY LTD (ACN 002 433 436)**

**KKT-SL300HP 30 Tonne Single Acting Compression Head ("The Crimper/Compression Head")**

Sold between 9<sup>th</sup> March 2010 and 16<sup>th</sup> May 2012

Serial Numbers SL00177 through to SL00856

The Compression Head is subject to recall

- Defect:** In two circumstances the hydraulic cylinder housing has burst around the base area causing high pressure hydraulic oil to squirt into the air.
- Hazard:** A stream of high pressure hydraulic oil can penetrate the skin and cause serious injury or death.
- What to do:** Customers must immediately cease using the Compression Head and contact their closest Specialised Force branch to arrange for the return of the Compression Head at our cost. Customers are entitled to a complete refund of the purchase price of the Compression Head. Alternatively, a customer may elect to receive a new replacement compression head that will work with their existing compression dies, battery pump and hose.
- No ban in force:** There is no interim ban or permanent ban on the Compression Head in force.
- Contact Details:** You can contact your local Specialised Force branch office or call our Head Office on 02 9547 1844 Monday – Friday 7:30am – 5:00pm.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information