

# ELECTRICAL SAFETY RECALL

**Nutriblend & NutriInfusion  
(Model XJ-13409 with Silver Stainless Steel Base)**



**Sold via the TV Shop & Live Events from March 2015 - September 2015**

**DEFECT:** An internal component of the blender is made of unsuitable material.

**HAZARD:** Risk of fire: If spilled liquid enters the internal parts of the blender it has the potential to cause fire.

**WHAT TO DO:** Customers should immediately stop using and register their details online [www.nutriinfusion.com.au/recall](http://www.nutriinfusion.com.au/recall) or call 1800 278 524 for information on how to return their product for repair free of charge.

**CONTACT DETAILS: Brand Developers Aust Pty Ltd**

For more information go to [www.nutriinfusion.com.au/recall](http://www.nutriinfusion.com.au/recall) or call 1800 278 524

**See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian Product Recall Information**