



Product Safety Recall



Do you own this product?

Fixed webbing seatbelt buckle for vehicle

An aftermarket seatbelt buckle that may have been fitted as a replacement part during vehicle repair.

Affected manufacturing dates: 1 July 2023 – 23 October 2023

Part numbers begin with '1765'.

Please see list of affected part numbers and traders list on the [Product Safety Australia website](#).

Dates sold: 3 July 2023 – 31 October 2023



Why the product is recalled: The stitching of the seatbelt may come apart and separate from the buckle.

Hazard: There is a risk of serious injury or death as the seatbelt may not properly restrain an occupant in the event of a car accident.



- Do not drive the vehicle if you think the affected seatbelt buckle is fitted to the driver's seat.
- Do not carry passengers in seats that you think might be fitted with the affected seatbelt buckle.
- Contact Hemco on 1300 065 057 or the store where you purchased it, or had it fitted. If it is recalled, Hemco will arrange a replacement to be fitted at no charge
- If the driver's seat belt is affected, Hemco will arrange for the vehicle to either be towed to the place of replacement or for a mobile technician to be sent to the vehicle (or similar arrangement), so that the vehicle does not have to be driven to receive a replacement.



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2024/20332

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information