

Product Safety Recall



Do you own this product?

Yamaha 4 and 6 seater golf cars

Models DR2A Fleet, PTV and SVC.

Dates sold: 1 January 2017 - 23 May 2023





Why the product is recalled: In affected golf cars, the headlight and USB plug fitted may not comply with the <u>Australian Electromagnetic Compatibility (EMC) standards</u>.

Hazard: There is a risk of electromagnetic inference with sensitive electrical equipment or impact on other electronic devices as a result of a radio frequency emitted from a non-compliant headlight or USB plug.



- Affected consumers should contact their local Yamaha dealer for an appointment to have the golf car inspected. If necessary, the part/s will be replaced free of charge.
- 2. Consumers can find their nearest authorised Yamaha dealer by visiting the Yamaha webpage.



For more information, contact Yamaha Motor Australia by phone 1300 277 137, email cr@yamaha-motor.com.au, or webform.



Purchased from: Authorised Yamaha dealers

PRA 2023/19830

See **productsafety.gov.au** for Australian product recall information